


6A2




Металлические связки: МГ-3 и МАГ-1

FEPA Form	D	H	d	S	h	Номер по каталогу
6A2	200	20	76(32)	10(5)	А К А З Ч И К	18.01
6A2	200	10	76(32)	10(5)		18.02
6A2	200	8	76(32)	10		18.03
6A2	200	6	76(32)	10		18.04
6A2	200	4	76(32)	10		18.05
6A2	200	2	76(32)	10		18.06
6A2	150	20	32(20)	10		З А К А З И Ю
6A2	150	15	32(20)	10	18.08	
6A2	150	12	32(20)	10	18.09	
6A2	150	10	32(20)	10	18.10	
6A2	150	8	32(20)	10	18.11	
6A2	150	6	32(20)	20(10)	18.12	
6A2	150	4	32(20)	20(10)	18.13	
6A2	150	2	32(20)	20(10)	П О Т Р Е Б О В А Н И Ю	18.14
6A2	125	6	50(32)	5		18.15
6A2	125	4	50(32)	5		18.16
6A2	125	2	50(32)	5		18.17

Размеры **H**, **d** и **h** могут быть изменены по требованию Заказчика

6A2



Металлические связки: МГ-3 и МАГ-1

FEPA Form	D	H	d	S	h	Номер по каталогу
6A2	100	10	32(20)	10	А К Ч И К А	19.01
6A2	100	8	32(20)	10		19.02
6A2	100	6	32(20)	10		19.03
6A2	100	4	32(20)	10		19.04
6A2	100	2	32(20)	10		19.05
6A2	80	10	20	5	З А К А З Ю	19.06
6A2	80	8	20	5		19.07
6A2	80	6	20	5		19.08
6A2	80	4	20	5		19.09
6A2	80	2	20	5		19.10
6A2	60	4	24	2	В А Н И	19.11
6A2	60	2	24	2		19.12
6A2	40	4	16	2	Р Е Б О В	19.13
6A2	40	2	16	2		19.14
6A2	32	6	10	6(3)	П О Т Р Е Б О В	19.15
6A2	32	4	10	6(3)		19.16
6A2	32	2	10	6(3)		19.17

Размеры H, d и h могут быть изменены по требованию Заказчика